

(Provincial)

660874

Serial No. Y

1-4-2021

Received from *ਕਾਂਗੜਾ ਨਗਰ ਨਿਗਮ ਪੰਜਾਬ ਸਰਕਾਰ*

with letter No. 91 dated 6-4-2021

the sum of Rupees 5000/-

in Cash/by Chcq on account of 5000/-

in *ਪੰਜਾਬ ਸਰਕਾਰ* payment of *ਕਾਂਗੜਾ ਨਗਰ ਨਿਗਮ*

Rs 5000/- Signature *[Signature]* 20.2.1.22

Sub Divisional Engineer,
Designation
Provl. Sub Division P.W.D
B & R, SANGRUR (Pb.)

4749-6/13-20,000X100-Pb. Govt. Press, Patiala.

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਸਪਰਿੰਗ ਡੇਲਜ਼ ਪਬਲਿਕ ਸਕੂਲ,
ਸੰਗਰੂਰ।

ਨੰਬਰ 3 ਮਿਤੀ 1-4.2021

ਵਿਸ਼ਾ ਸਾਲ 2021-22 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।
ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: SPS/APRIL 3/2021, ਮਿਤੀ 06.04.2021

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ
ਇੰਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ
ਜੀ। ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 5000/- ਜੀ.ਆਰ ਨੰ: 660874 ਮਿਤੀ 1-4.2021
ਰਾਹੀਂ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ
ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 91, ਮਿਤੀ 06-04-2021 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾਂ
ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

- ਜੀ -
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Part-II

Building Safety Report

Name of School: Springdales Public School (Sr. Sec). (Distt. Sangrur).

I have visited the above-mentioned School Building along with Sh. Gora Lal / Junior Engineer and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31/03/2022**


Sub Divisional Engineer
Provincial Sub Division PWD, B&R
Sangrur.